


REVISION			
REV.	DATE	DESCRIPTION	DRAWN BY



Notes,
1. To maximize output force and life of linear actuators, radial load on lead screws should be avoided or be kept at a minimum.

CUSTOMER		NOTICE TO PERSONS RECEIVING THIS DRAWING															
WIRING CHART		EXCITATION SEQUENCE				UNLESS OTHERWISE SPECIFIED ALL DIMENSIONS ARE IN MILLIMETERS AND TOLERANCES ARE AS BELOW PER ISO2768-ck.				DRAWN Alice DATE 2020/11/12		DINGS					
		CW \longrightarrow Red A+ + - Red/wht A- - + Green B+ + - Grn/wht B- - + CCW \longleftarrow				LINEAR		ANGULAR		APPRVD						DATE	
						0~3		±0.2		0~10		±1.5°		MODEL 14E21-150		SIZE A3 SHEET 1 OF 1	
						3~6		±0.5		10~50		±1°				SCALE 1: 1 REV 00	
						6~30		±0.8		50~120		±30'					
						30~120		±1.5		120~400		±15'					